Motor Vehicle Information Report



Vehicle Description

VIN	1FMCU9HD8JUC67194	Tank	
Year	2018	City MPG	
Make	Ford	Highway MPG	
Model	Escape	Anti-lock Brakes	4-Wheel ABS
Manufactured In	UNITED STATES	Steering Type	amp; Pinion;Rack &
Trim Level	SEL 4WD	Front Brake Type	Disc
Body Style	SPORT UTILITY 4-DR	Rear Brake Type	Disc
Engine Type	1.5L L4 DOHC 16V	Tires	P235/55R17
Transmission	6A;6-Speed Automatic	Power Door Locks	
Driveline	four-wheel drive	Vehicle Anti-Theft	Std
4WD/AWD			

SUMMARY

Information from VIN as of 05/29/2025 19:34

* The content of the report may be materially updated following the report date.

Current Title Record	1	
Historical Title Record	3	
Title Brand Records	0	
Junk and Salvage Records	2	
Insurer "Total loss" Records	0	
Recall Record	1	

Title Information Last Title on record with NMVTIS

VIN	1FMCU9HD8JUC67194
Title Issue Date	01/28/2022
Odometer	93,366 M
Please note: The odometer reading provided is as of the titling date and does not represent the current odometer	

reading.

• If you would like additional information regarding the title from this jurisdication, please click here

3 previous titles found				
State	VIN	Issued On	Odometer	DMV Link
MO	1FMCU9HD8JUC67194	11/16/2021	92,996 M	<u>click here</u>

- If you would like additional information regarding a vehicle title, click here for contact information
- Please note: The odometer reading provided is as of the titling date and does not represent the current odometer reading.

Title Brand Information 0 Brands found on this VIN

• A "brand" is recorded on a vehicle's title if it was ever junked, salvaged, rebuilt, or flooded, etc. There are many different types of brands. (A complete list of all Brand Definitions is included in this report.)

We have checked the following brand **categories** in the VIN database, and found no evidence that this vehicle has been branded:

- Salvaged/Junked/Totaled
- Flood Damaged
- Commercial Use
- Odometer Issues
- Prior Theft

- Rebuilt/Reconstructed/Repaired
- Damaged
- Fire/Hail
- Cash for Clunkers

(A complete list of all Brand Definitions is included in this report)

Junk and Salvage Information

Explanatory Note:

If this VIN has a record in the **Junk/Salvage or Insurance information** then the business that submitted the VIN to NMVTIS deemed the vehicle to be either a *junk, salvage, or in the case of an insurer, a total loss.* The information in the **DISPOSITION** field in the Junk/Salvage section denotes what has happened to the VIN (i.e., vehicle) since it came into the possession of the business.

▲ JUNK AND SALVAGE OPERATOR INFORMATION

VIN:	1FMCU9HD8JUC67194
Date Obtained:	08/05/2021
Disposition:	SOLD
Description:	Vehicle has been sold.
Intended for export:	NO
Name of Reporting Source:	COPART INC.
City of Reporting Source:	DALLAS
State of Reporting Source:	ТХ
Phone Number of Reporting Source:	9723099399
Email Address of Reporting Source:	NMVTIS.REPORTING@COPART.COM

JUNK AND SALVAGE OPERATOR INFORMATION

VIN:	1FMCU9HD8JUC67194
Date Obtained:	08/05/2021
Disposition:	TO BE DETERMINED

Description:	
Intended for export:	NO
Name of Reporting Source:	COPART INC.
City of Reporting Source:	DALLAS
State of Reporting Source:	ТХ
Phone Number of Reporting Source:	9723099399
Email Address of Reporting Source:	NMVTIS.REPORTING@COPART.COM

- Date Obtained: The date the vehicle was designated "junk", "salvage" or a total loss by an insurance company or anyone reporting on their behalf.
- If you have questions regarding the information provided by this reporting entity, please contact them at the telephone number or email address above.

NOTE: The above record for this vehicle indicates that it has probably suffered major prior damage, although some Junk/Salvage operators may handle vehicles with little or no damage. Consumer groups highly recommend that you have any used or repaired vehicle inspected by a qualified technician that is independent of the seller.

Insurer "Total Loss" Information

No Information Found

Recall Information

RECALL	
Name:	TRANSMISSION SHIFTER CABLE BUSHING
VIN:	1FMCU9HD8JUC67194
Effective Date:	06/10/2022
Recall Last Date:	05/03/2023
Risk:	A damaged or missing bushing may prevent the vehicle from shifting into the intended gear, and cause the vehicle to move in an unexpected direction. Additionally, the vehicle may roll after the driver selects the Park position. Either scenario increases the risk of a crash or injury.
Remedy:	DEALERS WILL REPLACE THE UNDER HOOD SHIFT BUSHING AND ADD A PROTECTIVE CAP OVER THE SHIFT CABLE BUSHING, FREE OF CHARGE.
Risk Type:	fire
Description:	The bushing that attaches the shifter cable to the transmission may degrade.
Recall ID:	78341
NHTSID:	22V413000
OEMID:	FORD 22S43