

Motor Vehicle Information Report



Vehicle Description

VIN	1HGEJ8243WL103794	Tank	11.90
Year	1998	City MPG	28 - 30
Make	Honda	Highway MPG	35
Model	Civic	Anti-lock Brakes	
Manufactured In	UNITED STATES	Steering Type	amp; Pinion;Rack &
Trim Level	EX coupe	Front Brake Type	Disc
Body Style	COUPE 2-DR	Rear Brake Type	Drum
Engine Type	1.6L L4 SOHC 16V	Tires	185/65R14
Transmission	4A OD;4-Speed Automatic Overdrive	Power Door Locks	Std
Driveline	front-wheel drive	Vehicle Anti-Theft	

4WD/AWD

SUMMARY

Information from VIN as of 06/19/2025 02:28

* The content of the report may be materially updated following the report date.

Current Title Record	1
Historical Title Record	6
Title Brand Records	0
Junk and Salvage Records	0
Insurer "Total loss" Records	0
Recall Records	2

Title Information

Last Title on record with NMVTIS

CALIFORNIA TITLE

VIN	1HGEJ8243WL103794
Title Issue Date	11/20/2024
Odometer	EXEMPT

Please note: The odometer reading provided is as of the titling date and does not represent the current odometer reading.

- If you would like additional information regarding the title from this jurisdiction, please [click here](#)

6 previous titles found

State	VIN	Issued On	Odometer	DMV Link
CA	1HGEJ8243WL103794	02/26/2019	EXEMPT	click here

CA	1HGEJ8243WL103794	11/09/2018	EXEMPT	click here
CA	1HGEJ8243WL103794	03/12/2018	EXEMPT	click here
CA	1HGEJ8243WL103794	12/17/2015	EXEMPT	click here
CA	1HGEJ8243WL103794	03/18/2011	169,952 M	click here
CA	1HGEJ8243WL103794	05/28/2006	123,000 M	click here

- If you would like additional information regarding a vehicle title, [click here](#) for contact information
- Please note: The odometer reading provided is as of the titling date and does not represent the current odometer reading.

Title Brand Information

0 Brands found on this VIN

- A "brand" is recorded on a vehicle's title if it was ever junked, salvaged, rebuilt, or flooded, etc. There are many different types of brands. (A complete list of all Brand Definitions is included in this report.)

We have checked the following brand **categories** in the VIN database, and found no evidence that this vehicle has been branded:

- Salvaged/Junked/Totaled
- Flood Damaged
- Commercial Use
- Odometer Issues
- Prior Theft
- Rebuilt/Reconstructed/Repaired
- Damaged
- Fire/Hail
- Cash for Clunkers

(A complete list of all Brand Definitions is included in this report)

Junk and Salvage Information

Explanatory Note:

If this VIN has a record in the **Junk/Salvage or Insurance information** then the business that submitted the VIN to NMVTIS deemed the vehicle to be either a *junk, salvage, or in the case of an insurer, a total loss*. The information in the **DISPOSITION** field in the Junk/Salvage section denotes what has happened to the VIN (i.e., vehicle) since it came into the possession of the business.

NOTE: No Junk/Salvage information was found in the **VIN** records, for this vehicle. However, most consumer groups highly recommend that you have any used or repaired vehicle inspected by a qualified technician that is independent of the seller.

Insurer "Total Loss" Information

No Information Found

Recall Information



RECALL

Name:	Airbag Inflators May Rupture Or Underinflate Bag
VIN:	1HGEJ8243WL103794
Effective Date:	01/17/2020

Recall Last Date:

05/22/2025

Risk:

In the event of a crash necessitating airbag deployment, an inflator rupture may result in metal fragments striking the driver or other occupants. An underinflated airbag cushion may not properly protect the occupant. These scenarios increase the risk of serious injury or death.

Remedy:

DEALERS WILL INSPECT THE DRIVER FRONTAL AIRBAG INFLATOR, AND REPLACE IT IF NECESSARY, WITH AN INFLATOR OF A DIFFERENT DESIGN.

Risk Type:

safety

Description:

Injury Risk - Airbag inflators may rupture or underinflate bag

Recall ID:

29074

NHTSID:

20V026000

OEMID:

20-008 / D8J



RECALL

Name:

Floormat

VIN:

1HGEJ8243WL103794

Effective Date:

05/20/1999

Recall Last Date:

05/22/2025

Risk:

The floor mat could prevent the accelerator pedal from returning to the idle position.

Remedy:

IF A CUSTOMER HAS A GENUINE HONDA DRIVER-SIDE FLOOR MAT, DEALERS WILL INSTALL A POSITIVE FLOOR MAT RETENTION SYSTEM CONSISTING OF A GROMMET IN THE FLOOR MAT AND A PIN BRACKET IN THE CAR.

Risk Type:

collision

Description:

Collision Risk - Potential floor mat interference with accelerator pedal

Recall ID:


14207

NHTSID:

99E015000

OEMID:

K60

Recall data provided by  .

[Click here](#) for a list of Title Brands.
