

Motor Vehicle Information Report



Vehicle Description

VIN	2G1WC57MX91282262	Tank	17.00
Year	2009	City MPG	18
Make	Chevrolet	Highway MPG	28
Model	Impala	Anti-lock Brakes	4-Wheel ABS
Manufactured In	CANADA	Steering Type	amp; Pinion;Rack &
Trim Level	2LT	Front Brake Type	Disc
Body Style	SEDAN 4-DR	Rear Brake Type	Disc
Engine Type		Tires	225/55R17
Transmission	4A OD;4-Speed Automatic Overdrive	Power Door Locks	Std
Driveline	front-wheel drive	Vehicle Anti-Theft	Std
4WD/AWD			



SUMMARY

Information from VIN as of 05/28/2025 09:07

* The content of the report may be materially updated following the report date.

Current Title Record	1
Historical Title Record	8
Title Brand Records	5
Junk and Salvage Records	2
Insurer "Total loss" Record	1
Recall Record	0

Title Information

Last Title on record with NMVTIS



UTAH TITLE

VIN	2G1WC57MX91282262
Title Issue Date	05/09/2024
Odometer	EXEMPT

Please note: The odometer reading provided is as of the titling date and does not represent the current odometer reading.

- If you would like additional information regarding the title from this jurisdiction, please [click here](#)

8 previous titles found

State	VIN	Issued On	Odometer	DMV Link
-------	-----	-----------	----------	----------

UT	2G1WC57MX91282262	05/18/2023	EXEMPT	click here
CA	2G1WC57MX91282262	01/06/2022	145,746 M	click here
AR	2G1WC57MX91282262	08/15/2019	UNKNOWN	
AR	2G1WC57MX91282262	10/11/2018	UNKNOWN	
MO	2G1WC57MX91282262	06/15/2018	133,492 M	click here
MO	2G1WC57MX91282262	04/06/2018	134,082 M	click here
MO	2G1WC57MX91282262	02/09/2018	134,082 M	click here
MO	2G1WC57MX91282262	02/24/2010	825 M	click here

- If you would like additional information regarding a vehicle title, [click here](#) for contact information
- Please note: The odometer reading provided is as of the titling date and does not represent the current odometer reading.

Title Brand Information

5 Brands found on this VIN

- A "brand" is recorded on a vehicle's title if it was ever junked, salvaged, rebuilt, or flooded, etc. There are many different types of brands. (A complete list of all Brand Definitions is included in this report.)



Rebuilt

Branded On	12/29/2022
Branded By	UT

The vehicle, previously branded "salvage", has passed anti-theft and safety inspections, or other jurisdiction procedures, to ensure the vehicle was rebuilt to required standards. Also known as prior salvage (salvaged).



Rebuilt

Branded On	01/06/2022
Branded By	CA

The vehicle, previously branded "salvage", has passed anti-theft and safety inspections, or other jurisdiction procedures, to ensure the vehicle was rebuilt to required standards. Also known as prior salvage (salvaged).



Not Actual

Branded On	06/15/2018
Branded By	MO

The odometer reading is known to be other than the true mileage for the vehicle.



Salvage

Branded On	04/06/2018
Branded By	MO

Damage or Not Specified - Any vehicle which has been wrecked, destroyed or damaged, to the extent that the total estimated or actual cost of parts and labor to rebuild or reconstruct the vehicle to its pre-accident condition and for legal operation on roads or highways exceeds a jurisdiction-defined percentage of the retail value of the vehicle. The retail value of the vehicle is determined by a current edition of a nationally recognized compilation (to include automated data bases) of retail values.

Salvage--Damage or Not Specified also includes any vehicle to which an insurance company acquires ownership pursuant to a damage settlement, or any vehicle that the vehicle's owner may wish to designate as a salvage vehicle by obtaining a salvage title, without regard to extent of the vehicle's damage and repairs, or any vehicle for which the jurisdiction cannot distinguish the reason the vehicle was designated salvage.



Not Actual

Branded On	04/06/2018
Branded By	MO

The odometer reading is known to be other than the true mileage for the vehicle.

Junk and Salvage Information

Explanatory Note:

If this VIN has a record in the **Junk/Salvage or Insurance information** then the business that submitted the VIN to NMVTIS deemed the vehicle to be either a *junk*, *salvage*, or *in the case of an insurer, a total loss*. The information in the **DISPOSITION** field in the Junk/Salvage section denotes what has happened to the VIN (i.e., vehicle) since it came into the possession of the business.



JUNK AND SALVAGE OPERATOR INFORMATION

VIN:	2G1WC57MX91282262
Date Obtained:	12/07/2017
Disposition:	SOLD
Description:	Vehicle has been sold.
Intended for export:	NO
Name of Reporting Source:	COPART, INC.
City of Reporting Source:	DALLAS
State of Reporting Source:	TX
Phone Number of Reporting Source:	9723915299
Email Address of Reporting Source:	



JUNK AND SALVAGE OPERATOR INFORMATION

VIN:	2G1WC57MX91282262
Date Obtained:	12/07/2017
Disposition:	TO BE DETERMINED
Description:	
Intended for export:	NO
Name of Reporting Source:	COPART, INC.
City of Reporting Source:	DALLAS
State of Reporting Source:	TX
Phone Number of Reporting Source:	9723915299
Email Address of Reporting Source:	

- Date Obtained: The date the vehicle was designated "junk", "salvage" or a total loss by an insurance company or anyone reporting on their behalf.
- If you have questions regarding the information provided by this reporting entity, please contact them at the telephone number or email address above.

NOTE: The above record for this vehicle indicates that it has probably suffered major prior damage, although some Junk/Salvage operators may handle vehicles with little or no damage. Consumer groups highly recommend that you have any used or repaired vehicle inspected by a qualified technician that is independent of the seller.

Insurer "Total Loss" Information



INSURER OPERATOR INFORMATION

VIN:	2G1WC57MX91282262
Date Obtained:	03/07/2018
Name of Reporting Source:	TRADERS INSURANCE COMPANY
City of Reporting Source:	KANSAS CITY
State of Reporting Source:	MO
Phone Number of Reporting Source:	8163335030
Email Address of Reporting Source:	DVELAZQUEZ@TRADERSAUTO.COM

- Date Obtained: The date the vehicle was designated "junk", "salvage" or a total loss by an insurance company or anyone reporting on their behalf.
- If you have questions regarding the information provided by this reporting entity, please contact them at the telephone number or email address above.

NOTE: The above record for this vehicle indicates that it has probably suffered major prior damage, although some Junk/Salvage operators may handle vehicles with little or no damage. Consumer groups highly recommend that you have any used or repaired vehicle inspected by a qualified technician that is independent of the seller.

Recall Information

No Information Found

[Click here](#) for a list of Title Brands.

